

Attachment A

Summary of Distribution Circuit Field Inspection by ICC Staff			
Utility:	CILCO	Date:	7/17 & 18/01
Circuit:	036-002 (Eureka)	Inspector:	J. D. Spencer, G. E. Rockrohr, J. L. Prange
Gen. Notes: The maps provided were very difficult to use, with multiple circuits on the same map, duplicate maps, and other maps not needed. Some roads were not labeled. Most of the downguys throughout the circuit did not have guy markers. Extra lightning arresters and grounds have been added at several locations.			
Map No.	Item Description	Photo(s)	Location
5 of 14 (3 of 11)	Single phase spacer cable out of spacer (2 locations)		In N-S easement west of S. Hilldale Ave. going north from W. Gloria Dr., and in E-W easement south of W. Gloria Dr. going east from S. Forest Park Dr., Eureka
5 (8 of 11)	Trees close to primary		4H Park Rd. east of tap to Sta. 320759
7	Split pole top		CR 625 north & east from Sta. 320653
8	Split pole top		1st pole south of Sta. 320644 in tap going north from CH 8
9 (1 of 3)	Split crossarm	A8	At Sta. 320636 at north end of spur on CR 1600
10	Split crossarm		Along CR 800 at CR 1700
10	Split pole top	A9, 10, 11	5th pole south of CR 700 on CH 8 (1st pole south of tap to Sta. 320642)
12	Split crossarm		Along CR 1700 north of CR 900
13 (1 of 2)	Crossarm brace disconnected from arm	A12	Along 1000N (not labeled on map) just west of CR 1625
14	Split crossarm (field side)		Along CR 1700 south of Sta. 320620 (4th pole from end of line)